

MATERIAL SAFETY DATA SHEET

SECTION 1 - General Information

PRODUCT NAME	T2 Automatic X-Ray Developers Concentrate, Part 2				
PRODUCT USE	Photographic solution	HMIS SCALE	HEALTH 1	FLAMMABILITY 0	REACTIVITY 0 PPE C
SUPPLIER	White Mountain Imaging	CATALOG # 4010D, 4010D-ADM, 4010D-AG, 4010D-DP, 4010D-EX, 4010D-LA, 4010D-MR, 4010D-MV, 4010D-UM, 4200D,			
ADDRESS	P.O. Box 216 Salisbury NH 03268				
PHONE NO.	603-648-2124	EMERGENCY TEL #	CHEMTREC 800-424-9300		

SECTION 2 - Product and Hazardous Ingredients Information

HAZARDOUS INGREDIENTS	CAS NUMBER	W/W %	Permissible Exposure Limit	LD50	LC50
Water	7732-18-5	60-75	not listed	Not	Not available
Gluteraldehyde bis-bisulfite	7420-89-5	20-40	not listed	not available	not available

SECTION 3 - Hazards Identification

EFFECTS OF ACUTE EXPOSURE TO PRODUCT

Harmful if swallowed.

EFFECTS OF CHRONIC EXPOSURE TO PRODUCT

None known

SECTION 4 - First Aid Measures

SKIN CONTACT

Wash exposed skin thoroughly with soap and water. If irritation persists seek medical advice.

EYE CONTACT

Flush eyes with water for 15 minutes. Seek medical advice if symptoms persist.

INGESTION

DO NOT induce vomiting. Seek medical attention immediately.

INHALATION

If inhaled, remove to fresh air.

SECTION 5 - Fire Fighting Measures

FLAMMABILITY YES NO IF YES, UNDER WHAT CONDITIONS

MEANS OF EXTINCTION

As needed to extinguish adjacent fire source.

FLASHPOINT (°C) AND METHOD Not appropriate	UPPER FLAMMABLE LIMIT (% BY VOLUME) Not appropriate	LOWER FLAMMABLE LIMIT (% BY VOLUME) Not appropriate	AUTOIGNITION TEMPERATURE (°C) Not appropriate
HAZARDOUS COMBUSTION PRODUCTS See "Hazardous Decomposition Products".	EXPLOSION DATA Not susceptible	SENSITIVITY TO IMPACT Not susceptible	SENSITIVITY TO STATIC DISCHARGE Not susceptible

SECTION 6 - Accidental Release

Flush to sewer with plenty of water, if permitted. If not, soak up with dry absorbent material. Consult with governmental regulatory agencies for appropriate disposal of this material. Wear splash goggles, impervious gloves and apron.

SECTION 7 - Handling and Storage

Read and follow the label, material safety data sheet, and instructions before using. Avoid any contact with skin and eyes. Keep container tightly closed. Avoid incompatible substances. Wash thoroughly after handling this product.

SECTION 8 - Exposure Controls

VENTILATION Good general ventilation.

SKIN Latex or nitrile

EYE Splash goggles

RESPIRATORY

OTHER Eye wash station

SECTION 9 - Physical and Chemical Properties

PHYSICAL STATE Liquid	ODOR AND APPEARANCE Clear, off-white to pale yellow liquid			ODOR THRESHOLD Not available
VAPOUR PRESSURE (mmHg) < 17 mm Hg	VAPOUR DENSITY (Air = 1) 0.6 mm Hg	EVAPORATION RATE (Water = 1) Not available	BOILING POINT 212°F	FREEZING POINT 32°F
pH 2.90	SPECIFIC GRAVITY 1.075	SOLUBILITY IN WATER (20°C) Complete	COEFF WATER OIL Not available	PERCENT VOLATILE (BY VOLUME) Not available

SECTION 10 - Stability and Reactivity DataCHEMICAL STABILITY YES NO IF NO, UNDER WHAT CONDITIONS
Strong reducing agents and strong bases

INCOMPATIBILITY WITH OTHER SUBSTANCES IF YES, WHICH ONES?

YES NO

REACTIVITY, AND UNDER WHAT CONDITIONS Stable under ambient pressure and temperature.

HAZARDOUS DECOMPOSITION PRODUCTS None

SECTION 11 - Toxicological Information

EXPOSURE LIMITS

None known

IRRITANCY OF PRODUCT

Skin: Irritant

SENSITIZATION TO PRODUCT

None known

CARCINOGENICITY

Not listed by IARC,
OSHA or ACGIH.

TERATOGENICITY

Not known

REPRODUCTIVE TOXICITY

Not known

MUTAGENICITY

Not known

SYNERGISTIC PRODUCTS

Not known

SECTION 12 - Ecological Information

No data available

SECTION 13 - Disposal Considerations

Dispose of this product in accordance with federal, state and/or local laws.

SECTION 14 - Transportation Information

Not regulated for transportation

SECTION 15 - Regulatory Information

SARA Section 304, CERCLA Hazardous components - (None)

SARA Section 302,304,313 Hazardous components (None)

Not a controlled product under Canadian WHMIS regulations.

SECTION 16 - Other Information

The information contained in this MSDS is furnished without warranty of any kind. The user should consider this data a supplement to other data gathered and must make an independent determination of suitability from this and other sources to assure proper use and disposal of this material and the health and safety of employees and customers.